



# WIRING DIAGRAM

## CTC STANDARD

### M12 TRIAXIAL SENSORS



4 Pin mini-MIL

- Pin 1 Axis Y
- Pin 2 Axis X
- Pin 3 Axis Z
- Pin 4 Common

